COSTUMER	ONYX SOLAR ENERGY, S.L.
ADRESS	C/ RIO CEA 1-46 05004 ÁVILA (SPAIN)
ASSOCIATED REPORT No.	055158-001-2 055158-002-2 055158-003-2 055158-004-2

## SAMPLE TESTED

Laminated glass made of two sheets of toughened glass of 6 mm, two layers of PVB of 0.76 mm and photovoltaic silicon float glass of 3.2 mm referenced as follows:

## «636-BN-»

## CONDUCTED TEST

The tests requested are that of

- Impact resistance in accordance with UNE-EN 12600:2003
- Manual attack in accordance with UNE-EN 356:2001
- High temperature in accordance with UNE-EN ISO 12543-4:2011
- Humidity in accordance with UNE-EN ISO 12543-4:2011

## RESULT

Impact resistance Manual attack High temperature Humidity Class 1B1 Class P4A SATISFACTORY SATISFACTORY

 Test dates
 21.03.2016 – 19.04.2016

 Date issued
 20.04.2016

These results are the summary of the data included in the Test Report identified above as the associated test Report No.

The results obtained in these tests only refer to the sample(s) analysed at this centre on the date shown, and do not involve a sample referring to production quality.

A Atto		
Signed: Susana Santamaría		
Technical Consultant		
Construction - Services		